

# Flight Report Aug 29, 2010

Submitted by **abansemer** on Sun, 09/19/2010 - 09:53

- **CAPS/CSI/PIP**
- **Earl**

Flight Date:

Sunday, August 29, 2010

The PIP failed again during turbulence 1:10 into flight. PIP repair will need to wait until we return to FLL.

Mostly small particles on this flight. All other instruments worked well.

Status:

Yellow